
Version 0.96 2019-05-14

- * Introducing simple user input locking in additon to password locking.
- * Fixed regression with non-zero start code sACN data packets.

Version 0.95 2019-05-02

- * Merging can now be turned off.
- * The refresh rate can now be changed between max. (ca. 44 Hz) and relaxed (ca. 30 Hz).
- * Fixed a merging bug that could leave the device in a state where it was impossible to send channel values to the outputs below a certain minimal level.
- * Reworked DMX generation engine.
- * Firmware version is now reported correctly via Art-Net.
- * Changed RDM buffers to correct size. The buffer size was low before, which could lead to crashes of the device.

Version 0.93 2018-05-17

- * Cleaner initialization.

Version 0.92 2018-05-16

- * Improved Art-Net and sACN network traffic filtering.
- * Optimized RDM table of device memory organization.
- * Changes to memory management.
- * Fix: Display content used to appear shifted occasionally.
- * DMX outputs are now turned off if low supply voltage is detected.
- * Improved displaying of fatal errors.

Version 0.91 2017-11-20

- * All RDM UIDs and MAC addresses are now listed in the device info screen.
- * Improved display of network address information.
- * Changed memory management:
 - All dynamically allocated memory is now managed by a single heap.

Version 0.90 2017-11-07

- * First release.